

AMENDMENTS TO THE DRAWINGS

The drawings have been amended to correct minor labeling errors.

FIG. 7: the reference number for the block labeled "PFD" has been changed from "80" to --25--.

FIG. 11: the label on the line connecting to M1 has been changed from "Vtb" to --Vfb--.

FIG. 14: the MOS switch connected to "Trimstart" has been labeled --M10--.

Three (3) replacement drawing sheets are enclosed.